



model VRK2AV

Valve Repair Kit For 5881

FEATURES & BENEFITS

OPTIONS

For more information, visit www.hawsc.com or call (888) 640-4297.



SPECIFICATIONS

Model VRK2AV is a Model 5881 valve repair kit that consists of spring, disc, diaphragm, and renew seat.

APPLICATIONS
